



# Manual de Instruções



|          |                                                                                     |      |          |                                                                                     |              |          |                                                                                     |              |          |                                                                                       |      |
|----------|-------------------------------------------------------------------------------------|------|----------|-------------------------------------------------------------------------------------|--------------|----------|-------------------------------------------------------------------------------------|--------------|----------|---------------------------------------------------------------------------------------|------|
| <b>A</b> |  | 1 PC | <b>F</b> |  | 1 PC         | <b>K</b> |  | 6x13mm 4 PCS | <b>L</b> |  | 1PCS |
| <b>B</b> |  | 1 PC | <b>G</b> |  | 4 PCS        | <b>L</b> |  | 4 PCS        |          |                                                                                       |      |
| <b>C</b> |  | 1 PC | <b>H</b> |  | 6x35mm 8 PCS | <b>M</b> |  | 1 PC         |          |                                                                                       |      |
| <b>D</b> |  | 1 PC | <b>I</b> |  | 12 PCS       | <b>N</b> |  | 1 PC         |          |                                                                                       |      |
| <b>E</b> |  | 1 PC | <b>J</b> |  | 12 PCS       | <b>K</b> |  | 6*50 12PCS   |          |                                                                                       |      |